- A. PX6856
- B. FILM EVALUATION REPORT
- C. TYPE LYC/3888
- B. FULTRON 202/MXSTE/AT" SECVET DEGREES F. /BAR 1.38- BAR 1.28
- 18. 2.8872.81
- F. 3404/2134/485-4-3-11-7
- 6. (1) GOOD
 - (2) NORMAL
 - (3) MEDIUM
 - (4) 0000
 - (5) OPERATIONAL
 - (6) HORMAL
 - (7) 99 PERCENT CLOUD COVER NORTH VIETNAMISH PERCENT CLOUD COVER OVERALL MISSOIN.
- W. O.W. DISPOSITION TO

25X1A

- 3 DUPE POS TO NATIONAL CUSTOMERS
- 6 DUPE POS 2 DUPE NEGS TO THEATER CUSTOMERS

25X1A

PAGE 4 MITS TOPSECRET

1. NORMAL STARTUP AND SHUT DOWN WITH CVERLAP IN FIRST 16 FRAMES
1/8" TO 3/4"AITO FRAMES. 1/RIK OF FORWARD CLOCKS IN IMAGERY
EVERY OTHER FRAMES APPROX 1/8" INTO FRAME. BACK ABBRASSIONS 2"
15 FROM TRAILING EDGE FROM 810 TO NO OF MISSION. RECYCLYING FROM
936 THROUGH 910. PRESSURE MARKE DW BASE SIDE. BIBEAKS WERE NOTED ON
HASE OF PART 647 3" INCHES IN FROM LEADING EDGE. MINUS DENSITY
STREAMS IN FORWARD FRAMES NOTICABLE ONLY IN MORIZON ON FORWARD
FRAME. PLUS DENSITY STREAMS WERE APPARENT IN HORIZON ON FORWARD
FRAMES RUNNING FROM LEADING TO TRAILING EDGE. FACTORY SPLICE IN
FRAME 1192. PINHOLE IN 641 1/2" IN 1 5/4" FROM TITLING SIDE. PART 12
100 NUMEROUS MANDLING SCRATCHES THROUGHOUT. MARKE 842, 1886, 1932,
1891 HAD NUMEROUS HANDLING SCRATCHES. 1888-1565 2 ACRATCHES 5
INCHES IN 1/4" APART, FRAMES 721-726 WERE OVERLAPED. 751, 134
HAD S STREAMS RUNNING VERTICAL. FRAMES 1988-1318 WERE FOR.

BEST COPY Available

	120		. 9 th 60 cu	2 9 y
	oz de c 180			
	FT P5 14/0900152 ZFF4 ZP0		25X1A	: :
	BT &		į	Aller J. •
	XXXXX		1 2	
			25X1A	
		g p		
				t e e e e e e e e e e e e e e e e e e e
		}	25X1A	
	TOPSECRET 090010Z MARCH	68 CIT		
Г		<u> </u>		
Ļ]	25X1A	
	A. 9X3356	· ·		1wa
	B. INS TAPE EVALUATION REPORT	, ,		
	C. INS010			ere en
The state of the s	D. 8/1232Z	and the second		
	E. 1. SATISFACTORY	à Linux Principes agression		
	2. SATISFACTORY	!		
	3. SATISFACTORY	r r		\bigcap
	4. SATISFACTORY			Con
	5. SATISFACTORY			
	6. SATISFACTORY			
	7. SATISFACTORY			
	8. SATISFACTORY			
(Mayan	9. SATISFACIORY	elle Medicale a la consideration de repaire	The second secon	erthre communicate to the series of
	10. SATISFACTORY			
	F. A LINE OF DATA WAS GARBLED BETWEEN ELAPSED TIME 7907 AND 7917.			
	TWO LINES OF DATA WERE DISPLACED TO THE LEFT BETWEEN ELAPSED			
	TIME 7917 AND 7931. ONE LINE OF	F DATA WA	S DISPLACED TO	THE LEFT
25	X1A			. is ,
	PAGE T O P S E C I	RET		
BETWEEN ELAPSED TIME 8015 AND 8024. THREE LINES OF DATA WERE				A WERE
	DISPLACED TO THE LEFT BETWEEN ELAPSED TIME 8052 AND 8071. TAPE			
	APPEARS SATISFACTORY. ERRORS CAN BE SALVAGED. TAPE EVALUATION			
	PERTAINS TO CAMERA OPERATION OF	NLY.		ř.
	100 etc. 105 etc. des etc. etc. etc. etc.			

01800010015-3

BT